

Duct & Outside Air Humidity Units with RTD Temperature Transmitter Humidity Output (4 to 20mA, 0 to 5V, 0/2 to 10V), Temperature Output (4 to 20mA)

Installation and Operating Instructions


26415\_ins\_hum\_RTD\_temp\_trans\_duct\_out

rev. 01/12/16

## Overview

The BA/T1x-(H2xx, H3xx) is a humidity transmitter which comes in 2% or 3% accuracies and an RTD temperature transmitter. It can be ordered for either Duct or Outside Air applications with a doublegang Weatherproof Enclosure (NEMA 3R) or a BAPI-Box Enclosure (NEMA 4, IP66). The humidity transmitter can be ordered with 4 to 20 mA, 0 to 5VDC, 0 to 10V or 2 to 10V output while the temperature transmitter has a 4 to 20mA output.

## **Duct Unit Mounting**







Fig. 1: Duct Humidity Unit in a Weatherproof (WP) Enclosure

Fig. 2: Duct Humidity Unit in a BAPI-Box (BB) Enclosure

Mount in the center of the duct wall at least 3 duct diameters from humidifiers. Drill a 1 inch hole in the duct for the probe and use two number 8 sheet metal screws to attach the sensor to the duct. Center the probe in its mounting hole. Be sure that the foam seals the hole, but do not over tighten the screws.

**Outside Air Mounting** 






Fig. 3: Outside Air Humidity in a Weatherproof (WP) Enclosure

Fig. 4: Outside Humidity Unit in a BAPI-Box (BB) Enclosure

Mount in a permanently shaded area away from windows and doors. Do not mount in direct sunlight. Mount with the sensor probe pointed down. Drill a hole large enough for your sensor cable through your mounting surface. Mount the unit to the surface with the wiring knock-out centered over the wiring hole. Pull the wiring into the unit and terminate using sealant filled connectors. Best practice is to seal the wiring hole with caulk after the wiring is installed. Be sure that the foam on the back of the unit makes a good weather tight seal.

Specifications subject to change without notice.



Duct & Outside Air Humidity Units with RTD Temperature Transmitter Humidity Output (4 to 20mA, 0 to 5V, 0/2 to 10V), Temperature Output (4 to 20mA)

Installation and Operating Instructions

26415\_ins\_hum\_RTD\_temp\_trans\_duct\_out

rev. 01/12/16

## Termination


Table 1: Humidty Transmitter with 4 to 20mA Output			
Wire Color	e Color Purpose Note		
White	Not Used	Not Used (Cap Wires)	
Black	Humidity Output	4 to 20 mA, To Analog Input of Controller	
Red	Power	10 to 35VDC	

Table 2: HumidityTransmitter with 0 to 5VDC Output			
Wire Color	Purpose Note		
White	Humidity Output	0 to 5VDC, To Analog Input of Controller	
Black	GND (Common)	Ground for Power and Humidity Output	
Red	Power	10 to 35VDC or 12 to 27 VAC	

Table 3: Humidity Transmitter with 0 to 10VDC Output			
Wire Color	Purpose Note		
Green	Humidity Output	0 to 10VDC, To Analog Input of Controller	
Black	GND (Common)	Ground for Power and Humidity Output	
Red	Power	15 to 35VDC or 15 to 27VAC	

Table 4: Humidity Transmitter with 2 to 10VDC Output			
Wire Color	Purpose Note		
Brown	Humidity Output	2 to 10VDC, To Analog Input of Controller	
Black	GND (Common)	Ground for Power and Humidity Output	
Red	Power	15 to 35VDC or 15 to 27VAC	

Table 5: Temperature Transmitter with 4 to 20mA Output			
Wire Color	Purpose Note		
Black	Temperature Output	4 to 20mA, To Analog Input of Controller	
Red	Power	7 to 40VDC	



Specifications subject to change without notice.

Duct & Outside Air Humidity Units with RTD Temperature Transmitter

Humidity Output (4 to 20mA, 0 to 5V, 0/2 to 10V), Temperature Output (4 to 20mA)

Installation and Operating Instructions



Specifications

rev. 01/12/16

Doworu				
Power: Units with RH Output of 4 to 20mA or 0 to 5VDC: Units with RH Output of 0 to 5VDC: Units with RH Output of 0 to 10VDC or 2 to 10VDC: Units with Temperature Output of 4 to 20mA:		10 to 35VDC, 22mA max 12 to 27VAC, 0.53VA max 15 to 35VDC, 6mA max or 15 to 27VAC, 0.14VA max 7 to 40VDC, 22mA max		
Humidity Sensor: Humidity RH Accuracy Drift Response time RH Linearity RH Hysteresis	Factory corrected @17 RH points (10 to 90% RH) Capacitive Polymer ±2% @ 73°F (23°C) from 10 to 90% 0.5% per year < 5 seconds in moving air Negligible, factory corrected linier from 10 to 90% Factory corrected to <1%			
Humidity Filter:	80 micron sintered stainless stee	el filter		
Humidity Transmitt Transmitter Output H200, H300 H200, H300 H210, H310 H212, H312		C, Voltag	e drop is 10VDC	
Humidity Sensor C RH 2% RH 3%	Calibrated Accuracy: Calibration @17 RH points, (10% to 90%) 2% from 10 to 90% @ 73°F (23°C), Non-condensing 3% from 10 to 95% @ 73°F (23°C), Non-condensing			
Output Wiring	2 wire current loop, or 3 wire voltage			
Transmitter Ambier				
Temperature Humidity	-4 to 158°F (-20 to 70°C) 0 to 100% RH, condensing			Platinum 1KΩ RTD
<b>Probe Ambient:</b> Temperature Humidity	-40° to 158°F, (-40° to 70°C) 0 to 100% RH, condensing		RTD Transmitter Out Transmitter Output	4 to 20mA, 850Ω@24VDC
Probe Length: Duct Outside Air	5.3" (13.5cm) Duct Insertion, 1" 2.4" (6.1cm) Below Enclosure, 1		Output Wiring Output Limits Span Min. Zero Min.	2 wire loop <1mA (short), <22.35mA (open) 30°F (17°C), Max 1000°F, (555°C) Min -130°F (-90°C)
Dimensions: Weatherproof (WP)	W x H x D 4.5" x 4.5" x 2.2", (114 x 114 x 55 (doublegang)	5 mm)	Zero Max Max 900°F (482°C)	
BAPI-Box (BB)	4.15" x 5" x 2.5", (105.4 x 127 x 63	3.5mm)	Power Output Shift	±0.009% of span
Enclosure Material: Weatherproof (WP) BAPI-Box (BB)	: Cast Aluminum (doublegang) Polycarbonate, UV resistant		RTD Sensor Transmitter Ambient	2 wire Platinum (Pt), 385 curve -4 to 158°F (-20 to 70°C) 0 to 100% RH, condensing
Enclosures Ratings Weatherproof (WP) BAPI-Box (BB)	s: NEMA-3R (doublegang) NEMA-4, IP66, UL94V-0	·		
<b>Termination:</b> Crimp Wire Nut	Open wire 18 to 26 AWG with Sealant Fille 26 to 16 AWG with Sealant Filled			00-x00)
Who Hut				
Approvals:	RoHs			

Specifications subject to change without notice.



Duct & Outside Air Humidity Units with RTD Temperature Transmitter Humidity Output (4 to 20mA, 0 to 5V, 0/2 to 10V), Temperature Output (4 to 20mA)

26415\_ins\_hum\_RTD\_temp\_trans\_duct\_out

Installation and Operating Instructions

rev. 01/12/16

## Filter Care

A filter protects the humidity sensor from various airborne particles that might reduce the sensor's accuracy. Depending on the sensor's location and environment, this filter may need periodic cleaning. To do this, gently unscrew the filter from the probe. Rinse the filter under warm water until clean. Warm soapy water may be used if necessary. Gently replace the filter by screwing it back into the probe. The filter should screw all the way into the probe. Hand tighten only. If a replacement filter or replacement probe is needed, call BAPI.

BA/HDOFS3 Stainless Steel Sintered Filter Replacement

Possible Problems:	Possible Solutions:
Unit will not operate	- Check for proper supply power. (See the wiring diagram and power specifications
Humidity output is at its maximum or minumum value	- Make sure the humidity sensor is wired properly.
Humidity reading in controller's	- Check all software parameters
software appears to be off by more than the specified accuracy	<ul> <li>Determine if the sensor is exposed to an external air source different from the measured environment, such as air infiltration through the wiring conduit.</li> </ul>
Output         Humidity Formula           4 to 20mA         %RH = (mA-4)/0.16           0 to 5VDC         %RH = V/0.05           0 to 10VDC         %RH = V/0.1           2 to 10VDC         %RH = (V-2)/0.08	<ul> <li>Check the Humidity transmitter output against a calibrated reference such as a 2% accurate hygrometer. Measure the humidity at the sensor's location using the reference meter, then calculate the humidity transmitter output using the humidity formula at left. Compare the calculated output to the actual humidity transmitter output (see the wiring diagram for the humidity transmitter output wire colors). If the calculated output differs from the humidity transmitter output by more than 5% contact BAPI technical support.</li> </ul>
Diagnostics - Temperature	
Possible Problems: Unit will not operate	<ul> <li>Possible Solutions:</li> <li>Check for proper supply power (7 to 40VDC) to the temperature transmitter. (See pages 2 for wiring diagram and power specifications.)</li> </ul>
Temperature sensor reading	- Determine if the input is set up correctly in the controller's front end software.
s inaccurate at the controller software	- Check if the RTD sensor wires are physically open or shorted.
	<ul> <li>Determine if the sensor is exposed to an external air source different from the measured environment, such as air infiltration through the wiring conduit.</li> </ul>
Temperature Equation $T = T_{low} + \frac{(A-4)x(T_{span})}{16}$ $T = Temperature at sensor$ $T_{low} = Low temperature of span$ $T_{high} = High temperature of span$	<ul> <li>Check the resistance of the temperature sensor (located inside the unit's probe) against an accurate temperature standard. Measure the temperature at the sensor's location using a reference meter. Disconnect the temperature sensor wires (2 Red Wires for a 100 Ohm Platinum RTD sensor or 2 Orange Wires for a 1,000 Ohm Platinum RTD sensor) and measure the temperature sensor's resistance with an ohmmeter. Compare this resistance to the appropriate temperature sensor's Output Table on the BAPI website. (Go to www.bapihvac. com; click on "Resource Library" and "Sensor Specs" and then on the 100 Ohm Plat. RTD or the 1,000 Ohm Plat. RTD.) If the measured resistance is different from the Output Table by more than 5%, contact BAPI technical support.</li> </ul>
T <sub>span</sub> = T <sub>high</sub> - T <sub>low</sub> A = Ammeter reading in mA	<ul> <li>Check the output current of the temperature transmitter (located inside the unit's enclosure) against an accurate temperature standard. Measure the temperature at the sensor's location using a reference meter. Measure the transmitter current by placing an ammeter in series with the controller input (the black wire on the temperature transmitter). The current should read according to the equation at le</li> </ul>

The temperature surrounding the transmitter must be between -4 and 158°F (-20 and 70°C).

Specifications subject to change without notice.

the wiring between the unit and the controller.

If the measured output is different from the calculated output, call BAPI technical

support. If the measured output is the same as the calculated output, then check